


LEDone®

3 in 1 Dimming Cable


Operation Manual

Capatible with PWM or 0-10V or Resistance dimmer


LOC-L07-01



Installation Method






Cable plug in the socket




Dimmer

The other end cable
go through the heat sink


3 Different Dim Signal Wiring




Other options



Microwave sensor



PIR sensor



Photocell sensor

LEDone®

Phone: (844) LEDONE6 | Fax: 1-510-217-9461 | Web: www.ledonecorp.com